

ZL-7816A Humidity and Temperature Controller

Version 1.1


2024-1-9

Introduction

- Easy to set.
- Professional sensor.
- Sensor cable can be extended to 50 meters.

Specification

- Sensor precision: Humidity $\pm 3\%$, Temperature $\pm 1\%$
- Set and display range: Temperature 0.0 ~ 80.0°C,
humidity 0 ~ 99.9%RH
- Working environment: -10 ~ 45°C, 5 ~ 95%RH without dew
- Power consumption: 2 watts
- Power supply: 12Vac, or 12Vdc
- Outputs: 7A / 250Vac each
- Sensor option: ZL-SHR04 or ZL-SHR05**



Setting

Keep [S] depressed for 2 seconds, enter into setting status:

The up window displays parameter code.

The bottom window displays the value of the code.

Press [S] to select the code. See the parameter table below for codes.

Press [▲] or [▼] to set the value (keeping depressed could fast set).

Keep [S] depressed for 2 seconds to exit, and the settings are saved.

Note: The status will exit if no key operation for 30 seconds, and the settings will be saved.

Parameter table:

Code	Function	Range	Remark	Factory set
tC	Cooling or heating	Co/HE	Co: cooling, HE: heating	HE
tSP	Setpoint	0.0 ~ 99.9°C	°C	37.5
td	Hysteresis	0.0 ~ 30.0°C		0.1
tCA	Calibration	-5.0 ~ 5.0°C	0.0: no calibration	0.0
tHA	Too high alarm	0.0 ~ 30.0°C	0.0: disable alarm	0.5
tLA	Too low alarm	0.0 ~ 30.0°C	0.0: disable alarm	1.5
HC	Humidify or dehumidify	H/P	H: humidify, P: dehumidify	H
HSP	Setpoint	0.0 ~ 99.9%RH		52.0
Hd	Hysteresis	0.0 ~ 30.0%RH		0.2
HCA	Calibration	-5.0 ~ 5.0%RH	0.0: no calibration	0.0
HHA	Too wet alarm	0.0 ~ 30.0%RH	0.0: disable alarm	10.0
HLA	Too dry alarm	0.0 ~ 30.0%RH	0.0: disable alarm	5.0
SHr	Sensor option	4/5	4: ZL-SHR04, 5: ZL-SHR05	5

Control

Temperature control

Heating control

When parameter $tC = HE$, heating control.

When temperature $\leq tSP - td$, temperature output energized.

When temperature $\geq tSP$, temperature output deenergized.

Cooling control

When parameter $tC = CO$, cooling control.

When temperature $\geq tSP + td$, temperature output energized.

When temperature $\leq tSP$, temperature output deenergized.

Humidity control

Humidify

When parameter $HC = H$, humidifying control.

When humidity $\leq HSP - Hd$, humidity output energized.

When humidity $\geq HSP$, humidity output deenergized.

Dehumidify

When parameter $HC = p$, dehumidifying control.

When humidity $\geq HSP + Hd$, humidity output energized.

When humidity $\leq HSP$, humidity output deenergized.

Alarming

Over temperature alarm

When temperature $\geq tSP + tHA$, high temperature alarms, up window displays "tHi".

When temperature $\leq tSP - tLA$, low temperature alarms, up window displays "tLo".

Over wet alarm

When humidity $\geq HSP + HHA$, high humidity alarms, bottom window displays "HHi".

When humidity $\leq HSP - HLA$, low humidity alarms, bottom window displays "HLo".

Calibration

The sensed temperature and humidity can be calibrated by set parameter TCA for temperature error, HCA for humidity error.

Display

When sensor has problem, or not connected, display "--.-".

When temperature output energized, its output lamp is on. When it is deenergized, the lamp is off.

When humidity output energized, its output lamp is on. When it is deenergized, the lamp is off.


Restore Setting

Keep \blacktriangle and \blacktriangledown depressed simultaneously for 2 seconds, display "UnL". Then press \blacktriangledown 3 times, there will be a long beep, the settings will be restored to factory default settings.

Attention

Install by certified technician. The outputs are not allowed to drive heavier loads than their specification. The PCB avoids to be in exposed to super wet condition.

Wiring



Installation

